

# Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

### **WORK ORDER INFORMATION**

Work Order Name: WO/10010MC1909/1

Work Order Type: Weatherization Audit Name: 10010MC1909

**CLIENT INFORMATION** 

Client Name: Address:

**Client ID:** 10010MC1909 MURFREESBORO, TN 37129

Alt. Client ID:

#### **AGENCY INFORMATION**

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Fax:

Address: P.O.Box 310, 233 Legend Drive, Suite 103

Lebanon, TN 37088-0310 Email Address:

Company Name & License Number:	
Contractor's Signature	

#### **COMMENT**

SITE BUILT 1957, 1456 SQ FT LEAD PAINT LIKELY

Client Name: Client ID: 10010MC1909 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/10010MC1909/1

Report Run On: 5/17/2010

DOE Weatherization Assistant Version 8.6.0 Page 1 of 11

## Measures

Measure 1 INSTA	ALL 2 SMOKE ALARMS	6		Componen	ts		,	nspected
Comment								
			Estimated	•		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	2 SMOKE ALARMS	Each	2					
Other Detail								
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								
	ALL 6 MIL VADOD BAD	DIED		Componen	<b>1</b> 0			nspected
Measure 2 INSTA	ALL 6 MIL VAPOR BAR FT; CONTRACTOR TO			Componen				nspected
Measure 2 INSTA	FT; CONTRACTOR TO			Estimated		Qty	Actual Unit Cost	
Measure 2 INSTA Comment 1170 SQ # Material / Labor		VERIFY	Qty 1	•		Qty	Actual	nspected Total
Measure 2 INSTA Comment 1170 SQ  # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1170 SQ # Material / Labor	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1170 SQ  # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY <i>Units</i>	Qty	Estimated		Qty	Actual	
Measure 2 INSTA Comment 1170 SQ  # Material / Labor Health and Safety	FT; CONTRACTOR TO  Description / Comment	VERIFY  Units  Each	<b>Qty</b> 1	Estimated			Actual	

	TEND BATHROOM EXHA SE TO EXTERIOR, APPR			Componen	ts		,	Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	y OTHER	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	AL PLUMBING PENETRA DER KITCHEN SINK	ATIONS		Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALNG	Each	1					
Other Detail						1		
			Measur	e Sub Total:		] :	Sub Total:	
Field Notes:								

UN	SEAL PLUMBING PENETRATIONS UNDER BATHROOM VANITY & COMMODE SUPPLY LINE (2)			Components				Inspected
Comment	,	•						
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:		]	Sub Total:	
	EATHER STRIP FRONT & OOR	BACK		Componen  Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	WEATHER STRIP	Each	1					
Other Detail								
Other Detail								
			Measur	e Sub Total:		] .	Sub Total:	
Field Notes:								

Measure 7 AD	D DOOR SWEEP TO FRO OR	ONT & BA	CK	Componen	ts		1	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Doors	DOOR SWEEP	Each	1					
Other Detail						] [		
						] []		
						] []	Sub Total:	
			Measur	e Sub Total:			Sub Total:	
Measure 8 SEA	AL CRACK UNDER BATI	HROOM		Componen	ts			Inspected
WII	AL CRACK UNDER BATI NDOW & TILE	HROOM		Componen				Inspected
WIN Comment	NDOW & TILE			Estimated	1	Oftv	Actual	
WIN Comment		HROOM  Units  Each	Qty 1	-		Qty		Inspected
WIN Comment # Material / Labor	NDOW & TILE  Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
WINCOMMENT  # Material / Labor Other	NDOW & TILE  Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
WINCOMMENT  # Material / Labor Other	NDOW & TILE  Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
WINCOMMENT  # Material / Labor Other	NDOW & TILE  Description / Comment	Units Each	Qty 1	Estimated	1		Actual	

	AL AROUND PIPE HOLE BINET IN BATHROOM	S IN		Componen	its		,	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Measure 10 INS	STALL SOFFIT BAFFLES	INI ATTIC						
		IN ATTIC		Componen				Inspected
# Material / Labor	Description / Comment			Estimated	1	Otv	Actual	
# Material / Labor Other	Description / Comment OTHER	Units Each	<b>Qty</b> 1	•		Qty		Inspected Total
Other	-	Units	Qty	Estimated	1	Qty	Actual	
	-	Units	Qty	Estimated	1	Qty	Actual	
Other	-	Units	Qty	Estimated	1	Qty	Actual	
Other	-	Units Each	<b>Qty</b> 1	Estimated	1		Actual	

Measure 11 Flo	or Ins. R-19			Componen	<i>t</i> s F1		ı	nspected
<b>Comment</b> CONTI	RACTOR TO VERIFY							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1170					
Other Detail								
			Measure	Sub Total:			Sub Total:	
Field Notes:								
West 2007 40 A44	- In - D 40			0	1- 04			Inapported
Measure 12 Atti				Componen	<i>t</i> s A1			nspected
	ic Ins. R-19 RACTOR TO VERIFY			Componen Estimated			I Actual	inspected
Comment CONTI		Units	Qty	-		Qty		Inspected
Comment CONTI	RACTOR TO VERIFY	<i>Units</i> SqFt		Estimated	1	Qty	Actual	
Comment CONTI	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
Comment CONTI # Material / Labor 1 Insulation	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
Comment CONTI # Material / Labor 1 Insulation	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown		Qty	Estimated	1	Qty	Actual	
Comment CONTI # Material / Labor 1 Insulation	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown	SqFt	<b>Qty</b> 1170	Estimated	1		Actual	
<ul><li>Comment CONTI</li><li># Material / Labor</li><li>1 Insulation</li></ul>	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown	SqFt	<b>Qty</b> 1170	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor  1 Insulation  Other Detail	PACTOR TO VERIFY  Description / Comment  Attic Insulation - Blown	SqFt	<b>Qty</b> 1170	Estimated Unit Cost	1		Actual Unit Cost	

Measure 13 REF Comment 45.5" X	PLACE BROKEN PANE   : 55.5"	IN WN-9-V	V	Componen	its		1	Inspecte
	39.5" X 23" RACTOR TO VERIFY							
OOMII	CACTOR TO VERILL			Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	PANE	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Measure 14 GL/	AZE WINDOW WN-8-W.	BACK OF		Componen	nts			Inspecte
НО	AZE WINDOW WN-8-W, USE 3"; CONTRACTOR TO V			Componen				Inspecte
HO Comment 28" X 6	USE		Qty	Componen  Estimated  Unit Cost		Qty	Actual Unit Cost	Inspecte
HO Comment 28" X 6	USE 3"; CONTRACTOR TO V	ERIFY		Estimated	ı	Qty	Actual	
HO Comment 28" X 6 # Material / Labor Windows	USE 3"; CONTRACTOR TO V  Description / Comment	ERIFY  Units	Qty	Estimated	ı	Qty	Actual	
HOIComment 28" X 6  # Material / Labor	USE 3"; CONTRACTOR TO V  Description / Comment	ERIFY  Units	Qty	Estimated	ı	Qty	Actual	
HO Comment 28" X 6 # Material / Labor Windows	USE 3"; CONTRACTOR TO V  Description / Comment	ERIFY  Units	Qty	Estimated	ı	Qty	Actual	
HOI Comment 28" X 6  # Material / Labor Windows	USE 3"; CONTRACTOR TO V  Description / Comment	VERIFY  Units  Each	<b>Qty</b> 1	Estimated	ı		Actual	

Measure 15 MAST	TIC SEAL REGISTERS	& RETU	RN	Componen	ts		ı	nspecte
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmen	MASTIC SEAL	Each	1					
Other Detail								
			Measur	e Sub Total:		] ;	Sub Total:	
Field Notes:								
riela Notes.								
ried Notes.								
		VE 5 FOR		Componen	te			nspecte
Measure 16 INTA	LL AIR FILTER & LEA\ EOWNER	VE 5 FOR		Componen	ts		-	nspecte
Measure 16 INTAI	EOWNER	VE 5 FOR		Componen	ts			nspecte
Measure 16 INTAI	EOWNER	VE 5 FOR		<b>Componen</b> Estimated			I Actual	nspecte
Measure 16 INTAI HOMI Comment 20" X 25'	EOWNER	VE 5 FOR  Units	Qty	-		Qty		nspecte
Measure 16 INTA	EOWNER  Description / Comment		<b>Qty</b> 1	Estimated	<u>'</u>	Qty	Actual	
Measure 16 INTAI HOMI Comment 20" X 25'  # Material / Labor Heating Equipmen	EOWNER  Description / Comment	Units	_	Estimated	<u>'</u>	Qty	Actual	
Measure 16 INTAI HOM Comment 20" X 25" # Material / Labor	EOWNER  Description / Comment	Units	_	Estimated	<u>'</u>	Qty	Actual	
Measure 16 INTAI HOMI Comment 20" X 25'  # Material / Labor Heating Equipmen	EOWNER  Description / Comment	Units	_	Estimated	<u>'</u>	Qty	Actual	
Measure 16 INTAI HOMI Comment 20" X 25'  # Material / Labor Heating Equipmen	EOWNER  Description / Comment	Units Each	1	Estimated	<u>'</u>		Actual	

	Measure 17 DWH	I Pipe Insulation			Componen	ts		ı	nspected
C	omment								
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail								
							] []		
				Measur	e Sub Total:		]	Sub Total:	
	Measure 18 DWH	I Tank Insulation			Componen	ts		1	Inspected
		I Tank Insulation			Componen Estimated			Actual	Inspected
С		I Tank Insulation  Description / Comment	Units	Qty	-		Qty		Inspected
<i>C</i>	omment Material / Labor		<i>Units</i> Each		Estimated		Qty	Actual	
<b>C</b> # 1	omment Material / Labor	Description / Comment		Qty	Estimated		Qty	Actual	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm  Labor	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm  Labor	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1	Estimated		Qty	Actual	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm  Labor	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1 1	Estimated			Actual	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm  Labor	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1 1	Estimated Unit Cost			Actual Unit Cost	
<b>C</b> # 1	omment  Material / Labor  Hot Water Equipm  Labor  Other Detail	Description / Comment DHW Tank Insulation	Each	<b>Qty</b> 1 1	Estimated Unit Cost			Actual Unit Cost	

#### Measure 19 INSTALL CRAWLSPACE DOOR (31.5" X Inspected **Components** 17") W/HINGES & HASP, 2 COATS **PAINT Comment CONTRACTOR TO VERIFY SIZE Estimated** Actual # Material / Labor **Description / Comment** Units Qty **Unit Cost** Total Qty **Unit Cost** Total Other **OTHER** 1 Each Other Detail Sub Total: Measure Sub Total:

Work Order Grand Total:	Grand Total:	

Field Notes: